



Date: 08/20/2010
Time: 1:00 – 2:00
Direction: Northeast
Photo by: Chris
Cahnovsky
Exposure #: 001
Comments: Dome
Building



Date: 08/20/2010
Time: 1:00 - 2:00
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 002
Comments: Dome
Building





Date: 08/20/2010
Time: 1:00 - 2:00
Direction: West
Photo by: Chris
Cahnovsky
Exposure #: 003
Comments: DIS
Building



Date: 08/20/2010
Time: 1:00 - 2:00
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 004
Comments: Inside Fines
Building. Covered
fines previously in
Fines Building






Date: 08/20/2010
Time: 1:00 – 2:00
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 005
Comments: Inside Fines
Building. Fines from
Tank House



Date: 08/20/2010
Time: 1:00 – 2:00
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 006
Comments: Lot
sweepings





Date: 08/20/2010 Time: 1:00 - 2:00 Direction: East Photo by: Chris Cahnovsky Exposure #: 007 Comments: Tank House



Date: 08/20/2010
Time: 1:00 - 2:00
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 008
Comments: Tank
House





Date: 08/20/2010 Time: 1:00 – 2:00 Direction: East Photo by: Chris Cahnovsky Exposure #: 009 Comments: Tank House



Date: 08/20/2010
Time: 1:00 - 2:00
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 010
Comments: Tank
House





Date: 08/20/2010
Time: 1:00 – 2:00
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 011
Comments: Hazardous
Materials in the
Tank House



Date: 08/20/2010 Time: 1:00 – 2:00 Direction: West Photo by: Chris Cahnovsky Exposure #: 012 Comments: Tank House